



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Osamu SAITO, et al.

Application No.: 10/749,374

749,374 ATTENTION

Confirmation No.: 9161

CERTIFICATE OF CORRECTION

Filed: January 2, 2004

BRANCH

Certificate

U.S. Patent No.: 6,904,819

JAN 3 0 2006

Issued: June 14, 2005

of Correction

For:

MONITOR FOR INJECTION MOLDING MACHINE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date:

Bv:

H J Steas

Registration No. 22,010

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

JAN 31 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

CERTIFICATE OF CORRECTION

PATENT NO: 6,904,819

DATED: June 14, 2005

INVENTOR(S): Osamu SAITO, et al.

Column 2, line 23, after "variables" insert --,--.

Column 10, line 62, change "back pressure" to --backpressure--.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005 PATENT NO. 6,904,819

No. of add'l copies @ 50¢ per page